US ERA ARCHIVE DOCUMENT

UNIT LOG Unit Name/Designators Situation Unit		1. Incident Name Kalamazoo River/Enbridge Oil Spill 5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		2. Date Prepared 11/24/2012	3. Time Prepared	
				f	6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012	
ı			Personnel Ros	ster Assigned		
Name			ICS Position		Home Base	
Matthew Haak			Situation Unit Leader		Chicago, IL	
Time			Activity Log	t o		
71me 0730	· Arrive a	Arrive at ICP				
08:00						
	· Arrived C0.4 boat launch, sweep boat arrived and launched the boat.					
	• MP5.15 – MP5.63 LDB no sheen or ice observed.					
	· MP5.63 LDB no sheen or ice observed.					
	· MP5.63 RDB observed a very thin layer of ice beginning to form.					
	 MP 5.75 RDB, observed a very thin layer of ice beginning to form within the vegetation along the shoreline. 					
	Ceresco Dam control point, no ice observed forming along the boom.					
	· Ceresco Dam control point, observed sheen and tar globs collecting within the debris along the boom.					
	 Ceresco Dam control point, observed spontaneous sheen and tar globs. 					
	· Ceresco Dam impoundment no ice observed forming along the LDB.					
	 MP5.5 Center channel observed sheen and tar globs. Quantity of sheen and tar globs would not warrant a sweep boat. 					
11:00	· Arrived at the E4 boat launch, sweep boat was waiting.					
	Morrow Lake north cove no sheen or ice observed.					
	 Morrow Lake south cove no sheen or ice observed. 					
	Morrow Lake Delta control point anchors remain. Observed a set of anchor poles with boom marker missing.					
	Morrow Lake Delta near former Gate D located lost section of boom.					
	· SWAT crew replaced the section of boom marking the anchor poles.					
	 Morrow Lake Delta observed sheen and tar globs. 					
	 MP21.5 Custer Bridge no sheen or ice observed. 					
	APD15 5 0 11 ACID 1 1 1 1 1					
13:30	Return to ICI	P. Prepare pho	oto log and 214.			

Matthew Haak, Situation Unit Leader, USEPA-START